
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 7/15/2009
Test to be performed: Smoke Dyed Water X	Ground Condition.	
Manhole_ID: S03UU_021MH	Test ID: <u>D1032-022005</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S03UU_021MH
0			Water Level	
30.70000076	10		Tap Factory Active	From 4014 Norfolk
30.70000076			Dye Test Visible	@ TF - cleanout
30.70000076			Dye Test Visible	@ TF - under downspout
30.70000076			Manhole	S03UU_028MH
30.70000076			End of Survey	DYE TESTS COMPLETED